

Initial Spill Report					
Name & Company:	Ken Barnes- Orica Canada Inc				
Date & Time Observed:	June 14, Approx 18:00				
Fluid Spilled:	Dry Ammonium Nitrate	Fluid Quantity (L)	500Kg		
Location & Description of Spill Area	Silo pad and ground beside 10U 372362.00m 5893709.00m				
Spill to:	☒ Ground	☐ Water	Photos Taken:	☒ Yes	☐ No
Equipment/Source of Spill:	60 Tonne and Silo				
Circumstances/Cause of Spill:	Slide gate operating chain derailed				
Spill Response Actions Taken:	Source of the spill was stopped. Material had a tarp placed over top and weighted down to protect from precipitation. Prills and contaminated material on ground were cleaned up immediately and bagged.				
Contaminated Material Disposal Methods:	Contaminated material was bagged and will be used in future blasts by being placed in bore holes on pattern.				
Reportable Spills					
Responsible Persons:	Ken Barnes				
Reported to Spill Hotline	☒ Yes	☐ No	DGIR #	252356	
Date & Time Reported:	15:11, 15-June-2025				
Government Agencies Notified:	Ministry of Environment				
Government or First Nation Agencies At Spill Site:	N/A				