

Initial Spill Report					
Name & Company:	Dan O'Neil - BWG				
Date & Time Observed:	May 17, 2025 – 4:00 PM				
Fluid Spilled:	Coolant/Antifreeze	Fluid Quantity (L)	132		
Location & Description of Spill Area	MSA/Mobile Maintenance Pad				
Spill to:	☒ Ground	☐ Water	Photos Taken:	☒ Yes	☐ No
Equipment/Source of Spill:	Haul Truck 1504				
Circumstances/Cause of Spill:	Coolant hose failure, line from engine to cab.				
Spill Response Actions Taken:	Spill response was initiated immediately. Spill was contained with spill cleanup booms, 2.5 gallon buckets to catch spill and spill pads used to clean up material.				
Contaminated Material Disposal Methods:	Spill pads and booms were disposed of in hydrocarbon impacted waste GFL bins. Contaminated material was disposed of in contaminated soil/snow bins.				
Reportable Spills					
Responsible Persons:	Mark Warbanski				
Reported to Spill Hotline	☒ Yes	☐ No	DGIR #	251947	
Date & Time Reported:	May 18, 2025 - 8:24 AM				
Government Agencies Notified:	BC Spill Hotline				
Government or First Nation Agencies At Spill Site:	None				