

Initial Spill Report					
Name & Company:	Steven Hayward, BWG				
Date & Time Observed:	May 28				
Fluid Spilled:	Sewage/Waste Water	Fluid Quantity (L)	250		
Location & Description of Spill Area	Construction Camp Dorm 1				
Spill to:	☒ Ground	☐ Water	Photos Taken:	☐ Yes	☐ No
Equipment/Source of Spill:	Waste Water Pipe under Construction Camp				
Circumstances/Cause of Spill:	Cracked pipe resulted in slow leak				
Spill Response Actions Taken:	Vacuum trucks were mobilized and put through confined space training. Spilt liquid was drained using Hydro-Vac truck and material removed. Hydrated lime was used to disinfect area and fans used to dry area.				
Contaminated Material Disposal Methods:	Waste water was disposed of off-site by 3 rd party vendor with trucks designed for waste water.				
Reportable Spills					
Responsible Persons:	Alan Matthews				
Reported to Spill Hotline	☒ Yes	☐ No	DGIR #	252415	
Date & Time Reported:	June 18, 19:00				
Government Agencies Notified:	Ministry of Environment				
Government or First Nation Agencies At Spill Site:	Environmental Assessment Agency				