

Initial Spill Report				
Name & Company:	Adam Scott Artemis Gold Inc.			
Date & Time Observed:	November 27, 2025 04:45am			
Fluid Spilled:	Hydraulic Fluid	Fluid Quantity (L)	430	
Location & Description of Spill Area	1560 Bench West 53.169870° , -124.870020°			
Spill to:	☒ Ground	☐ Water	Photos Taken:	☒ Yes ☐ No
Equipment/Source of Spill:	Hydraulic Leak for the Swing Circuit of SH3601			
Circumstances/Cause of Spill:	Mechanical failure. A hydraulic leak occurred in the swing circuit of the SH3601			
Spill Response Actions Taken:	Truck was shut down, Dispatch was informed. Maintenance was dispatched out to stop the leak. Spill tray placed under area of leak. Deployed absorbent pads around area Lube truck evacuated all surface hydrocarbon had pooled 988 loader collected all soiled material and loaded into 773 HT			
Contaminated Material Disposal Methods:	Loaded onto 773 HT and brought to PAG waste storage area.			
Reportable Spills				
Responsible Persons:	KC Whitney, Artemis Gold Inc.			
Reported to Spill Hotline	☒ Yes	☐ No	DGIR #	254581
Date & Time Reported:	November 27, 2025 16:49			
Government Agencies Notified:	Ministry of Environment			
Government or First Nation Agencies At Spill Site:	N/A			